


920XC Trace Viewer Interpretation


VER 1.1

920XC Trace Viewer Interpretation



VER 1.1


920XC Trace Viewer Interpretation



Event Table								
No.	Type	Locatio...	Refl.[dB]	Ins.Loss[dB]	Attn.[dB/km]	Cum.Loss[dB]	Dist.Prev.[km]	Dist.End[km]
1	Start	0.0000	-46.107	-,---	-,---	-,---	-,---	37.9391
2	Refl.	25.2757	-35.711	1.091	0.184	4.643	25.2757	12.6634
3	End	37.9391	-29.008	-,---	0.186	8.093	12.6634	-,---

Bulkhead
Bad connector
End of fiber

920XC Trace Viewer Interpretation




VER 1.1

920XC Trace Viewer Interpretation



920XC Trace Viewer Interpretation



Sales and Technical Support

Greenlee Communications

1390 Aspen Way

Vista, CA, 92081

www.greenlee.com

1- 800-642-2155

Contact your local Greenlee location or representative for pricing.